

Appendix 3

RESC11-08-08 – Utilities - Water Supply Exceptions

Date	Location	What	Why	Remedial Action
12/05/2011	88 Valley	Reservoir low level	Insufficient flow from intake.	Repaired leak in intake pipeline, cleaned filters, partly cleaned out intake. Stream too high for complete cleanout.
19/05/2011	Motueka – north end of Thorp Street	200 dia PVC main break.	Insufficient cover to main. Low grade pipe	Repaired with new section of higher grade pipe.
03/06/2011	Richmond – Talbot Street	100 dia AC main break.	Pressure fluctuation during pump test with reservoir isolated.	Repaired with new section of pipe. Cut back to one pump.
20/06/2011	Tapawera – Main Road / Rata Avenue corner	150 dia AC main break.	Disturbance from nearby construction work.	Repaired with new section of pipe.
20/06/2011	Dovedale – Dove River	150 dia steel main break under river. Five day interruption to supply.	Cause not yet known as river still too high to access pipe.	Temporary pipe bridge installed across river using a bridge beam mould from Thelins. 100 dia steel pipe laid through steel mould casing. Water delivered by tanker to some properties.
22/06/2011	Mapua – Stafford Drive	200 dia PVC main break.	Fragile pipe.	Repaired with new section of pipe.