

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
5958	5/05/10	High Street, from the roundabout to Staples Street	Power poles on western side need repainting for the first 2 metres height. Reflector discs also needed on these poles to improve safety.		These are not require to be painted white or have reflectors as they are in a restricted speed zone and behind the kerbing.	28/02/11	DO
37976	14/07/10	Pathway from Motueka Memorial Hall to Poole Street, Motu	Pathway needs more lighting, particularly near tennis club. This has become a hang out spot and there is now regular vandalism occurring. The senior citizens have also had vandalism occur. The pathway also needs to be lifted up outside the tennis clubrooms because as soon as it rains the path is then under water.		No budget allocated to providing lights in this location. To be discussed with Reserves Manager.		DO
38248	11/08/10	Glenaven Drive, Motueka	Retention ponds in Glenaven Drive do not drain properly after heavy rain. The drain is higher than the surrounding land and the land needs raising up to the same level to enable the water to disappear.		Waiting for cooler weather (probably April) to spread soil and allow for better seed strike		DO
10362	8/11/10	2A Greenwood Street	Carpark has a lot of weeds and litter in it. Mr Ogilvie would like this area marked with carparking spaces		Weeds and detritus have been cleared, pavement repairs have been programmed, which will be followed by pavement markings		DO
10434	10/11/10	Hickmott Place	No Parking" lines needed on the east side of Hickmott Place. If vehicles are parked on this side of the road any traffic coming from Tudor Street has to travel on the wrong side of the road to get past. There is a parking bay on the west side of this road.		Included in proposed bylaw changes		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
11438	20/12/10	52 Tudor Street	Sealing repairs required outside 52 Tudor Street. A temporary job was done some weeks ago. But the seal has deteriorated		Programmed and should be completed by end of April. Part of network repairs		DO
11439	20/12/10	Old Wharf Road	Sealing repairs required at the northern end of Old Wharf Road, east of Thorp Street		To be programmed and prioritised		DO
11441	20/12/10	Wilkie Street	Seal Repairs required on Wilkie Street, south of Parker Street intersection, to Fry Street		Crack seal to be completed during the April sealing season.		DO
40494	2/02/11	Greenwood Street	Street lighting is poor. The lights seem underpowered. Please check this and the quantity of light, as there are about 3 lamp-posts that do not have a light on them. Only posts on the norht side of road.		No faults found. Light levels to be looked at		DO
40496	2/02/11	TDC Service Centre	Hedging at rear of service centre seems to have vine invading hedge. Could vine be removed and shrubs pruned.		Order printed 03/02/11. Still to be actioned 24/02/11		DO
12215	2/02/11	35 Greenwood Street	Boundary hedge is overgrowing footpath		Letter sent out. Unsatisfactory action so follow up letter sent.		DO
12216	2/02/11	Greenwood Street	Hedges at 63, 68 and 70 need trimming		Two out of three completed as at 23/02/11		DO
40594	9/02/11	Old Wharf Road	Guard rail on the edge of Thorp Drain between Goodman Park and 76 Old Wharf Road is covered in algae and needs cleaning		Passed to MWH 09/02/11		PH
12332	14/02/11	Tudor Street	Tudor/Thorp Street sign post has been removed from top of road and dumped.			10/02/11	DO