

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
38248	11/08/10	Glenaven Drive, Motueka	Retention ponds in Glenaven Drive do not drain properly after heavy rain. The drain is higher than the surrounding land and the land needs raising up to the same level to enable the water to disappear.		Still to be planted		DO
13520	20/04/11	High Street and Courtney Street corner	In a previous request it was asked for a sign to be erected on the corner of High Street and Courtney Street directing people to the Jack Inglis Hospital. The reply received was that the hospital did not want the sign. At the Community Board meeting in April Cr Jack Inglis stated that a sign would be acceptable as long as it was worded "Jack Inglis Friendship Hospital"		style chosen, under construction by MWH		DO
16067	22/09/11	Motueka Quay	Deep potholes and considerable edge-break at the Motueka Quay cul-de-sac. This area will need some gravel, as well as a re-seal.			20/10/11	DO
42908	22/09/11	Goodman Park	Fence between Goodman Park and the Woodlands Drain needs the wire tightened on it and the standards straightened. There is also gorse growing along the fenceline that needs removing		works order with contractors to be actioned		DO
42912	22/09/11	Goodman Park	The sportsfields are carrying a lot of weeds and not much grass. On the western edge, nearing the drain the grass is very sparse. Mr Ogilvie would like the fields levelled, as there are many uneven patches and re-grassed.		On the spraying maintenance contract, so will be sprayed for weeds. No re-seeding is planned for this season.		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
16071	22/09/11	Rest-a-while' Rest area	There are accacia seedlings and new growth needing to be removed. Mr Ogilvie would also like a cypress and hebe, which partly obscure the sign, removed		Passed to Opus 27/09/11		DO
42913	22/09/11	Thorp Bush	There are 3 tracks through Thorps Bush. Mr Ogilvie believes the central track is unnecessary and should be closed by putting low (50cm) log style fencing in. He believes the other 2 are sufficient, but these need some maintenance done on them. The timber border has broken in places and some graveling is required. He would like low (50cm) log-style fencing installed to discourage cyclists from riding 'off track' and damaging plantings.		Will be discussed at meeting with Parks and Reserves staff		DO
42914	22/09/11	Memorial Park	Maintenance issues: 1. The pinnacles of the park gates need repainting. 2. Walkway gates from Poole Street can be an access problem for wheelchairs/mobile scooters/prams. This gate should be removed and the space repaired. Near the tennis club pavillion there are 3 gates, one could be removed to provide better access. 3. Stormwater problem outside tennis pavillion is still to be resolved.		This is being actioned. Work in progress		DO
42919	22/09/11	Marahau River Bridge	Marahau Bridge, just past Marahau Valley Road turnoff has a build up of debris under it. Can this be removed and the area around the foundations cleaned please.		With contractors		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
42922	22/09/11	Harbour Road	Between the corner of Edwin Chambers Drive and Thorp Street, Harbour Road seems dark and may need more lighting		Added to Council's priority matrix to be looked at in the future		DO
16465	12/10/11	52 Tudor Street	Potholes need repairing. Service request 14909 was entered for this on 18 July and updated on 28 september that this was completed, however this has never been repaired. Please action urgently		More than just repairing potholes. More major maintenance work required and this is programmed in to be done		DO