

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
31809	24/06/09	North Street	The heavy rain in June has undermined the work done in this street. The potholes need refilling. Long term solutions are needed for drainage and footpathing. Local residents would like meeting to discuss options. CB is happy to arrange.		Work to be progressed as timeframes allow. Steve communicated with David re this. Steve is happy to meet with residents if required and the meeting is organised by the Community Board.		DO
952	27/08/09	Corner Trewavas Street & Everett Street	The new seal at this corner has not been properly applied and has lifted badly. (Contractor either Fulton Hogan or Concrete & Metals - He thinks FH). This is similar to the problem in Greenwood Street.		Waiting on FH to fix seal. Pencilled in for 15/16 February. This is the case for all the remedial work from last year's reseal sites		DO
2558	2/11/09	Riwaka-Sandy Bay Road	South side of hill needs edges resealing, particularly on the bends			8/12/09	DO
2559	2/11/09	Umukuri Road	road needs maintenance by approaches to Brooklyn School		Will be part of a road reconstruction. In the design process at present		DO
2768	23/11/09	Corner Wilkie Street and Jocelyn Ave	Street sign on the corner needs to be secured at the base			1/12/09	DO
2769	23/11/09	Tudor Street	Chevron arrow outside number 40 is bent. May need replacing			27/01/10	DO
2785	26/11/09	King Edward Street	There needs to be a sign in King Edward Street at the approach to High Street showing the distance and direction of the I-Site		existing i-site sign in King Edward Street showing 3km to i-site		DO
4093	8/01/10	Riwaka-Kaiteriteri Road	Roadside litter cleanup required from Cooks corner, Riwaka-Kaiteriteri corner turnoff through to the Kaiteriteri bridge.		removed 7 rubbish bags of rubbish	11/01/10	DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
4106	11/01/10	Wallace Street I-Site	Vandels have broken a "Liquor Ban Sign" on Wallace St outside the Information Centre Motueka. This has been broken with sharp edge left sticking up on path which is a danger to public Please could this be looked at as soon as possible. Thanks.		sign replaced	27/01/10	DO
4110	11/01/10	Corner Tudor St & Hickmot Place	sign for the wastewater dump station needs to be positioned correctly and made unable to be moved.			19/01/10	DO
4140	11/01/10	Tudor Street Thorp Street Intersection	Street sign on the corner needs to be positioned correctly and secured to make it immobile.			13/01/10	DO
4181	11/01/10	Boyce Street	No exit signs have been damaged. Both are old black and white street signs			19/01/10	DO
4191	11/01/10	Parker St, Atkins St	Old black and white sign needs replacing		ordered new signs 27/01/10		DO
4192	12/01/10	Brooklyn Rd, Umukuri Rd	A series of small potholes at this intersection are getting bigger and need to be repaired before the beginning of the apple season.		repaired 10 potholes	13/01/10	DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
35343	12/01/10	Reserve between Glenaven Drive and Claire Place, Motueka	With the recent rain the drainage pipes which lead to the estuary by 67-69 Motueka Quay, have had their flaps opened and seawater has entered and pushed up into the reserve. These drainage flaps need to be looked at so the seawater doesn't flow in (maybe blocked by stones). Also the stormwater/seawater doesn't completely drain away from the park. The land seems to be too low lying and leaves rather large deep ponds, which could be a safety concern.		Works order raised 12/01/10. Should be completed early February		DO
4360	22/01/10	Pah Street West, Motueka (west from number 93 to the Te Awhina Marae)	Four of the marker pegs that mark the separation of the carriageway from the footpath have been removed. These need to be replaced.		ordered new marker posts		DO
4362	22/01/10	84 - 88 High Street, Motueka	The concrete footpath in this area is broken and requires replacing. It is a reasonably busy walking area and it's repair is relatively urgent.				DO
4363	22/01/10	High Street South, Motueka	The footpath between the roundabout and Wildman Road needs improved maintenance. Weed growth both narrows the path and is an issue in the path. Mr Ogilvie suggests that given the residential nature of this street, a two-coat chip seal footpath would be an appropriate solution to the continuing costs of maintenance		sprayed edge of path, now waiting on vegetation to die		DO
4364	22/01/10	Kakapo Lane and Sanderlane Drive corner, Motueka	The give way sign at this intersection is down. Please re-position.			22/01/10	DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
35531	22/01/10	Thorp Drain, 95-97 Tudor Street, Motueka	Small trees, shrubs, weeds are blocking the outlet to Thorp Drain from Ledger Avenue. Needs to be completely cleared to improve stormwater flows.		Downers - Drain ID - Mot 001 Due Feb clearance		DO