

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
38248	11/08/10	Glenaven Drive, Motueka	Retention ponds in Glenaven Drive do not drain properly after heavy rain. The drain is higher than the surrounding land and the land needs raising up to the same level to enable the water to disappear.		Still to be planted		DO
13520	20/04/11	High Street and Courtney Street corner	In a previous request it was asked for a sign to be erected on the corner of High Street and Courtney Street directing people to the Jack Inglis Hospital. The reply received was that the hospital did not want the sign. At the Community Board meeting in April Cr Jack Inglis stated that a sign would be acceptable as long as it was worded "Jack Inglis Friendship Hospital"		Being quoted on		DO
14628	27/06/11	Woodlands Ave	No parking lines on the Woodland Ave corner, opposite New World entry need to be remarked. It seems to have been missed in the latest marking programme			7/09/11	DO
14629	27/06/11	Motueka township	All the pedestrian crossings in central High Street and those in Wallace and Greenwood Street need to be remarked		Not TDC road, passed to Opus to mark		DO
14630	27/06/11	Thorp Street	In Thorp Street just back from the corner of Fearon Street there is a macrocarpa tree that's lower branches are hanging over the drain and part of Thorp street. These need to be removed to improve sight lines for traffic			16/09/11	DO
14909	15/07/11	Tudor Street	Potholes need repairing outside 52 Tudor Street			16/09/11	DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
42907	22/09/11	Woodlands Drain	There is a lot of litter in this drain. It begins with the path from New World to Thorps Bush, through Thorps Bush along the cycleway.walkway to the floodgates at Old Wharf Road		With contractors		DO
16067	22/09/11	Motueka Quay	Deep potholes and considerable edge-break at the Motueka Quay cul-de-sac. This area will need some gravel, as well as a re-seal.		Major repairs are being quoted on at present and will probably be actioned in a couple of weeks if successful		DO
16068	22/09/11	Cnr Green Lane and Grey Street	Seal has broken up on the north west corner. Also the deging along Green Lane is very rough and needs resealing.		Programmed for re-sealing. Major works to be done in the next couple of months		DO
42908	22/09/11	Goodman Park	Fence between Goodman Park and the Woodlands Drain needs the wire tightening on it and the standards straightening. There is also gorse growing along the fenceline that needs removing				DO
42912	22/09/11	Goodman Park	The sportsfields are carrying a lot of weeds and not much grass. On the western edge, nearing the drain the grass is very sparse. Mr Ogilvie would like the fields levelled, as there are many uneven patches and re-grassed.				DO
16070	22/09/11	High Street - Wharf Road roundabout	This roundabout needs weeding, pruning and the plantings upgraded. Mr Ogilvie would like similar plantings as the 3 brothers corner roundabout has just had planted.		No budget in the Annual Plan		DO
16071	22/09/11	Rest-a-while' Rest area	There are accacia seedlings and new growth needing to be removed. Mr Ogilvie would also like a cypress and hebe, which partly obscure the sign, removed				DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
42913	22/09/11	Thorp Bush	There are 3 tracks through Thorps Bush. Mr Ogilvie believes the central track is unnecessary and should be closed by putting low (50cm) log style fencing in. He believes the other 2 are sufficient, but these need some maintenance done on them. The timber border has broken in places and some gravelling is required. He would like low (50cm) log-style fencing installed to discourage cyclists from riding 'off track' and damaging plantings.		Will be discussed at meeting with Parks and Reserves staff		DO
42914	22/09/11	Memorial Park	Maintenance issues: 1. The pinnacles of the park gates need repainting. 2. Walkway gates from Poole Street can be an access problem for wheelchairs/mobile scooters/prams. This gate should be removed and the space repaired. Near the tennis club pavillion there are 3 gates, one could be removed to provide better access. 3. Stormwater problem outside tennis pavillion is still to be resolved.				DO
42918	22/09/11	Motueka Central Town Area	Some poorly lit areas in the central town area that have caused control difficulties: Behind Memorial Hall, Kyosato Garden area, rear of shops along the lanes that run between Greenwood to Wallace Streets and Wallace to Tudor Streets. Can these areas be provided with security cameras or at least improved lighting. This is a starting point for cameras, may eventually belong to other departments as well.		No budget in Annual Plan		DO

SR No:	Date Raised	Location	Subject	Status From Dept	Progress	Date Completed	Requested By
42919	22/09/11	Marahau River Bridge	Marahau Bridge, just past Marahau Valley Road turnoff has a build up of debris under it. Can this be removed and the area around the foundations cleaned please.		With contractors		DO
42922	22/09/11	Harbour Road	Between the corner of Edwin Chambers Drive and Thorp Street, Harbour Road seems dark and may need mor lighting		Should be completed second week in October		DO