




Comparison of Water Quality for Swimming From 2004 to 2010


The graphs below serve to compare and contrast sites monitored as part of Council's bathing water quality monitoring programme. A 95th percentile is the value which is exceeded 5% of the time (ie the worst 5% of results are above this).



Rabbit Island 2004-10



Kaiteriteri 2004-10



Mapua Leisure Park 2004-10

