

Appendix 2 – RESC11-06-04 – Utilities

Wastewater Exceptions

Location	Date	CSR/Enquiry	Why	Remedial action
Takaka (91 Abel Tasman Drive)	18/03/11	Sewage smell.	Possibly due to mechanical checks, water blasting and extra loading.	Investigated and smell had gone.
Takaka (678 Abel Tasman Drive)	12/04/11	Pipe break repaired.	Small overflow.	Cleaned and disinfected.
Kaiteriteri (Tapu Bay)	18/04/11	Bad smell.		Checked by contractor and smell had gone.
Kaiteriteri (5 Tapu Bay)	26/04/11	Strong smell of sewage.		This was investigated by the contractor but nothing found.
Motueka (62 Greenwood Street)	28/03/11	'LPG gas' smell.		Contractor arrived and checked but no smell present.
Motueka (Woodlands Avenue SPS)	26/04/11	Multiple blockages in pump 2.		Cleared by the contractor.
Mapua	29/03/11	Odour at pumpstation	Retention of flow and lack of odour treatment	Installed temporary sprinkler system in pump station. Upgrade planned

Sewer Blockages/Overflows

Location	Job Number	Date	What	Why	Remedial action
Riwaka (60-64 Wharf Road)	41820	31/03/11	Blocked sewer drain.		Blockage cleared by contractor, no overflow occurred.
Pohara	41838	01/04/11	Split pipe 50m up the road from first marker peg at pump station. Resulted in small wet patch.		Line isolated and repaired. Cleared up and disinfected.
Pohara	41969	12/04/11	500m downstream of pump station – pipe break approx 0.1m ³ discharged.		Main replaced and cleaned up and disinfected.
Takaka	42078	20/04/11	Sewerage ponds inlet blocked	Fat build up.	No overflow, junction cleared.
Motueka King Edward St	41860	04/04/11	Pipe blockage.	Fat build up.	Cleared, no overflow.
Richmond 49 Wensley Rd	41983	13/04/11	Blocked sewer pipe – 2m ³ of wastewater discharged.		Cleared, Cleaned and disinfected.