



Photograph 1 Dam site looking downstream (A)



Photograph 2 Typical reach of river downstream of dam (between A and B)



Photograph 3 Upper quarry site looking upstream (B)



Photograph 4 Upper quarry site looking downstream (B)



Photograph 5 Most upstream dwelling – about 3.5 km below dam site (between B and C)



Photograph 6 Temporary dwelling – about 4.5 km below dam site (just above C)



Photograph 7 Dwellings opposite lower quarry site on left bank (just above D)



Photograph 8 House on opposite bank (right bank) at Fairdale (D)



Photograph 9 Typical reach between Fairdale and the guide camp (between D and E)



Photograph 10 Looking downstream towards Guide camp (circled) in the distance (E)



Photograph 11 Houses on right bank upstream of confluence with Wairoa (just above F)



Photograph 12 Intake and pump station on right bank at Irvines (between F and G)