


LEGEND

- Scree slope (Possible landslide scarp)
- Scree/Landslide
- Dip/strike of bedding
- Location A
- Photo reference to Appendix
- TP 14/SC 12
- T&T test pit (TP) & Scota Penetrometer (SC)
- Shallow scrape
- River
- Road
- Potential Borrow Area
- Terrace gravel



Tonkin & Taylor
Environmental & Engineering Consultants
D Auckland D Nelson D Christchurch D Hamilton D Wellington D Whangarei

DRAWN	DNV	Sep.06
DRAFTING CHECKED		
APPROVED		
CADFILE: P:\22032.002-F1_F2		
SCALES (AT A3 SIZE)		
1:2000		
PROJECT No.		
22032.002		

TASMAN DISTRICT COUNCIL
GEOTECHNICAL PRE-FEASIBILITY ASSESSMENT
Lee River Valley, Tasman
Investigation Location Plan – Dam Sites

FIG. No. **Figure 1**

REV. **0**